


## PRO II SERVICE BODY LENGTH ADAPTER BRACKET - NOT COMPATIBLE WITH THE PRO RACK

---

Part # : 31710



### Pro II Service Body Length Adapter Brackets

This length adapter plate allows adjustment of 3.25" forward or backward of the front legs of Pro II service body racks. This greater adjustability may be necessary if the service body length is not within the limits of Holman Pro II racks.

### Compatible Items:

- 70020